

TLCF Monthly Report Attachment (25 November 2009) - Learning for the Future



Training Area Walls and Ceiling South



Training Area Ceilings and Lights




Training Area Walls and Ceiling South East



Training Area South West



Training Area Walls and Ceiling North East



Training Area Entrance sealed to adjoining room



Training Area Walls and Ceiling North to Kitchen



Training Area, Disabled Wash Closet at end

TLCF Monthly Report Attachment (25 November 2009) - Learning for the Future



Training Area view to rear entrance



Rear entrance from outside building



Rear entrance store room walls



Rear entrance facing training area ahead



Rear entrance store room in use



Patio under construction



Rear store room ceiling



Patio walls sealed and prepared for rendering

TLCF Monthly Report Attachment (25 November 2009) – Learning for the Future



External patio wall (main entry to building)



Staircase leading up to Training Area



External side wall at rear of building



View of patio construction from below



Contractors taking their lunch break



Peter Perryman – Learning & Development Consultant



Building view from office below

Status

Patio roof construction being undertaken
External walls prepped for rendering
Internal walls and ceiling established